

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** CMC Real Estate Corporation 330 N Jefferson St Ste 305 Chicago IL 60661 Phone: (312) 575-0400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3109656	Former MWRR Alberton	Railroad Ave	Alberton	59820	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No
2 / 02 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** CMC Real Estate Corporation 330 N Jefferson St Ste 305 Chicago IL 60661 Phone: (312) 575-0400

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
3109657	Former MWRR Tarkio		Alberton	59820	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Temporarily Out of Use		5/5/1961 45 / No	Diesel 200	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No
2 / 02 Temporarily Out of Use		5/5/1961 45 / No	Gasoline 200	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613785	Mountain West Co Op Alberton	415 Railroad Ave	Alberton	59820	(406) 543-8383

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently In Use	3858	8/1/1997 08 / Ye	Gasoline 12,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / S2 Currently In Use	3859	8/1/1997 08 / Ye	Diesel 12,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / S3 Currently In Use	3860	8/1/1997 08 / Ye	Diesel 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
4 / S4 Currently In Use	3861	8/1/1997 08 / Ye	Gasoline 4,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Silver Dollar Ventures Inc PO Box 420038 Haugan MT 59842 Phone: (406) 678-4242

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3113289	Silver Express Exxon	Exit 16 & Interstate 90	Haugan	59842	(406) 678-4242

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3161	4/1/1994 12 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
2 / 02 Currently in Use	3162	4/1/1994 12 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
3 / 03 Currently in Use	3163	4/1/1994 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
4 / 04 Currently in Use	3164	4/1/1994 12 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Lincoln Development Company Inc PO Box 219 Missoula MT 59806 Phone: (406) 543-5493

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3105827	Saint Regis Exxon	Mullan Road & MT Highway 135 N	Saint Regis	59866	(406) 649-2407

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																									
1 / 01 Currently in Use	3630	1/1/1973 33 / No	Diesel 8,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					
2 / 02 Currently in Use	3631	4/22/1982 24 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					
3 / 03 Currently in Use	3632	4/22/1982 24 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					
4 / 04 Currently in Use	3633	4/23/1973 33 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Stangs Inc PO Box M Saint Regis MT 59866 Phone: (406) 649-2414

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3107503	Stangs Inc	12 Old US Highway 10 E	Saint Regis	59866	(406) 649-2414

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4105	8/1/1999 06 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4106	8/1/1999 06 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4107	8/1/1999 06 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Lindevco Inc PO Box G Saint Regis MT 59866 Phone: (406) 649-2407

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3107690	Saint Regis Travel Center	100 Mullan Road W	Saint Regis	59866	(406) 649-2407

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	3813	4/22/1985 21 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3814	4/22/1985 21 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	3815	4/22/1985 21 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Bonneville Power Administration 2520 US Highway 2 E Kalispell MT 59901 Phone: (406) 755-6202

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
3107747	Taft Substation	Randolph Creek Road	Saltese	59867	(406) 257-4385

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	478	10/1/1990 15 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Secondary Containment	Safe Suction	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** CMC Real Estate Corporation 330 N Jefferson St Ste 305 Chicago IL 60661 Phone: (312) 575-0400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3109659	Former MWRR East Portal		Saltese	59867	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No
2 / 02 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Mineral County 300 River St PO Box 550 Superior MT 59872 Phone: (406) 822-3561

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3102302	Mineral County Courthouse UST	300 River St	Superior	59872	(406) 822-3525

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S2 Currently in Use	4450	5/1/1994 12 / No	Heating Oil 5,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Durangos Inc PO Box 759 Superior MT 59872 Phone: (406) 822-4967

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3107433	Durangos Inc	204 4th Ave E	Superior	59872	(406) 822-4967

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3816	4/23/1984 22 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A●●DEFGHIJKL</div> <div>B●●EFGHIJKL</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3817	4/23/1984 22 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A●●DEFGHIJKL</div> <div>B●●EFGHIJKL</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3108719	Town Pump Inc Superior	403 Diamond Road	Superior	59872	(406) 822-4451

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2538	1/22/1970 36 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2539	1/22/1970 36 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2540	1/1/1986 20 / No	Diesel 12,000	STI-P3 Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	2541	1/1/1972 34 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	4840	1/1/1981 25 / No	Diesel 12,000	STI-P3 Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2543	1/1/1989 17 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	4841	1/1/1989 17 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	4842	6/9/2003 03 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

9 / 09	<b>4843</b>	6/9/2003	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td colspan="3"></td> <td>B</td> <td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> </table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L				B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
			B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
Currently In Use		03 / No	3,000	Double-Walled	Double-Walled								Yes   Yes   Yes																				

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3108916	Mountain West Co Op Superior	211 Mullan Road E	Superior	59872	(406) 543-8383

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 01 Currently in Use	1063	5/1/1986 20 / No	Gasoline 2,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 02 Currently in Use	1064	5/1/1986 20 / No	Gasoline 2,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 03 Currently in Use	1065	5/1/1986 20 / No	Gasoline 2,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** CMC Real Estate Corporation 330 N Jefferson St Ste 305 Chicago IL 60661 Phone: (312) 575-0400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3109661	Former MWRR Superior		Superior	59872	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No
2 / 02 Currently in Use		5/5/1961 45 / No	Diesel 250	Unknown None	Unknown None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No No No No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Mineral

**Owner Name and Address:** Cstore Inc dba S and S Foods PO Drawer G Saint Regis MT 59866 Phone: (406) 649-2407

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3112870	S & S Foods Inc 3112870	205 4th Ave E	Superior	59872	(406) 822-4837

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently in Use	1971	10/1/1992 13 / No	Diesel 3,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 03 Currently in Use	1970	10/1/1992 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 01 Currently in Use	1968	10/1/1992 13 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 02 Currently in Use	1969	10/1/1992 13 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed